

FURUNO

PACKING LIST FOR FAR2837S/12

Box 1 - RPU013S Wt: 22 Lbs. Dim: 12" x 19" x 21"

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	RPU013S	Processor Unit for S Band	1
2	000-165-800	Terminal Spanner Tool Big	1
3	000-147-417	Terminal Spanner Tool Small	1
4	000-538-118	Crimp Lug FV2-4	2
5	000-155-826	Fuse FGBO 10A (For AC)	4
6	000-155-780	Fuse FGBO 20A (For DC)	4
7	IME-352-10Z	Installation Manual	1
8	OME-351-90Z	Operator's Manual	1

Box 2 - RCU014 Wt: 10 Lbs. Dim: 8" x 11" x 19"

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	RCU014	Control Unit with Cable Assembly	1
2	100-306-251-10	Fixing Bracket	1
3	000-147-167	Grommet "G39"	1
4	000-166-468	"3M" Brand Bumper Cushion	3
5	000-881-447	Washer Head Screw M4 x 12	2
6	000-881-447	Washer Head Screw M4 x 12	4

Box 3 - Gearbox Wt: 234 Lbs. Dim: 25" x 22" x 46"

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	RSB098-080	Scanner Assy w/30KW S Band Xcvr	1
2	100-090-720	Lifting Fixture	2
3	100-090-730	Collar For Lifting Fixture	2
4	300-130-020	Seal Washer	8
5	100-091-112	Corrosion Proof Rubber Mat	2
6	000-165-800	WAGO Terminal Tool Big	1
7	000-108-424	Crimp Lug FV2-3	2
8	000-538-118	Crimp Lug FV2-4	3
9	000-538-123	Crimp Lug FV5.5-4	1
10	000-864-263	Spring Washer M12	8
11	000-167-446	Flat Washer M12	8
12	000-863-112	Hex Nut M12	16
13	000-807-825	Hex Bolt M12 x 70	8
14	000-864-260	Spring Washer M6	1
15	000-864-129	Flat Washer M6	1
16	000-863-109	Hex Nut M6	1
17	000-162-871-10	Hex Bolt M6 x 25	1
18	000-566-000	Grounding Wire "340MM"	1

For Internal Use Only	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
RPU013S	
Yes	Remarks
	008-535-940
	"
	"
	008-535-910
	008-535-930

RCU014	
Yes	Remarks
	008-535-610
	"
	"
	"
	CP03-25604

RSB098-080	
Yes	Remarks
	008-538-730
	"
	008-551-450
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"

FURUNO

PACKING LIST FOR FAR2837S/12

For Internal Use Only

Serial No. _____
 Checked By: _____
 Tech _____
 Date _____

PSU007-70-23	
<u>Yes</u>	<u>Remarks</u>
	008-538-740
	"

001-078-410	
<u>Yes</u>	<u>Remarks</u>

SN36AF/ANT12	
<u>Yes</u>	<u>Remarks</u>
	008-254-590-00
	"
	"
	"
	"

MU231CR	
<u>Yes</u>	<u>Remarks</u>
	008-535-990
	008-536-000
	008-536-010
	"
	"

Box 4 - PSU007-70-23			Wt: 3 Lbs. Dim: 8" x 8" x 9"
<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	PSU007-70-23	Power Supply Unit	1
2	000-108-424	Crimp Lug FV2-3	2
3	000-538-118	Crimp Lug FV2-4	6

Box 5 - 001-078-410			Wt: 58 Lbs. Dim: 12" x 19" x 21"
<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	001-078-410	30M Cable Assembly	1

Box 6 - SN36AF/ANT12			Wt: 455 Lbs. Dim: 162" x 31" x 31"
<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	SN36AF/ANT12	S Band Antenna 12'	1
2	300-640-811	Guide Pin	2
3	000-171-786	"O" Ring	2
4	000-162-780	Hex Bolt M10 x 25	10
5	000-167-232	Flat Washer M10	10
6	000-167-233	Lock Washer M10	10
7	000-158-483	3 Bond Silicone Adhesive	1

Box 7 - MU231			Wt: 32 Lbs Dim: 23" x 26" x 10"
<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>	
1	MU231	23" Color LCD Monitor	1
2	000-149-054	Cable 5M DVI	1
3	000-157-497	Fuse FGBO 2A	2
4	000-157-492	Fuse FGMB 6A	2
5	100-305-111	Panel Cover	4
6	100-305-120	Panel Hook	2
7	000-162-614	Tapping Screw M6x30	4

FURUNO

PACKING LIST FOR FAR2837S/12

Box 8 - FAR-231-BKT **Wt: 21 lbs. Dim: 21" x 19" x 13"**

	<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1	100-305-371-10	Hanger Stay 552mm	1
2	000-160-074-10	Plug	2
3	000-570-276-10	Snap Button	4
4	000-167-232-10	Flat Washer M10	2
5	000-167-233-10	Spring Washer M10	2
6	000-162-884-10	Hex Bolt M10X30	2
7	000-172-165-10	Binding Head Screw M4X10	8
8	000-162-949-10	Hex Washer Head Bolt M6X25	4
9	001-143-370-00	Spacer	4
10	001-467-540-00	Bracket Assy Left	1
11	001-467-550-00	Bracket Assy Right	1

For Internal Use Only	
Serial No. _____	
Checked By: _____	
Tech _____	
Date _____	
FAR-231-BKT	
<u>Yes</u>	<u>Remarks</u>